

MASCA PTY. LTD. T/AS

ABN:27 121 846 188

ROGERS TRAILER HIRE & SERVICE



3 ANTIMONY STREET, CAROLE PARK

PH: (07) 3271 1427 MOB: 0418 192 894 EMAIL: mitchell@rogersaxles.com.au

SERVICING TO ALL **ROGERS AXLE & SPRING WORKS P/L** COMPONENTS

Rogers Trailers Pty. Ltd. offers **FRIDAY AFTERNOON & SATURDAY MORNING SERVICING**

All servicing is carried out at the factory of Rogers Axle & Spring Works by Rogers Trailer Hire & Service.

To book your service please contact Mitchell Chambers on:

Ph: (07) 3271 1744

Mob: 0418 192 894

BRAKE SYSTEM SERVICE (Standard)

- Remove all brake drums & check for wear
- Inspect brake shoes for wear
- Remove brakes
- Check Camshaft rollers for wear
- Check anchor pins for wear
- Remove camshaft & check for wear
- Inspect inner & outer cam bushes for wear
- Re-grease bushes
- Re-assemble brakes
- Check existing bearings for wear
- Remove existing grease from hub
- Replace hub seal – Charged incurred
- Re-grease hub
- Fit hub & drum assembly to axle
- Replace axle washer – Charged incurred
- Re-torque axle nut
- Replace axle split pin – Charged incurred
- Adjust all brakes
- Test trailer air control system

\$ 180.00 + Replaced Parts + GST

Service based on 3 hour turnaround – additional time to be charged at \$60.00 per hour + GST

SUSPENSION SYSTEM SERVICE (Standard)

- Drop springs from hangers & rockers
- Inspect spring eye bushes & pins for wear
- Inspect springs for wear/damage
- Check hangers for wear
- Re-fit springs
- Drop rockers from hangers
- Check rockers for wear
- Check rocker bush & pins for wear
- Re-fit rockers
- Re-torque spring & rocker bolts
- Replace U-Bolts – Charged incurred
- Re-torque u-bolts

\$ 210.00 + Replaced Parts + GST

Service based on 4 hour turnaround – additional time to be charged at \$60.00 per hour + GST

NOTE:

Any damaged or worn items found during servicing which are unsafe for re-fitting will be replaced at owners expense without consultation. Any worn items not requiring immediate replacing will be provided to owner in writing for replacement at next service

